


BENCH TEST

40-350, 352, 380, 382



Set-up: Connect ground (battery negative) to motor housing for all tests.
Note: power source must be 15-amp minimum.

LOW speed test:

1. Ground terminal P2
2. +12VDC to terminal L, motor runs high speed

HIGH speed test:

1. Ground to terminal P2
2. +12 VDC to terminal H, motor runs high speed

Park test:

1. +12 VDC to terminal P1
2. Attach jumper wire to terminal P2 and L, motor cycles once and parks.